

SAFETY RECALL

Step2 Push Around Buggy, And Whisper Ride Buggy

Model: 715700, 792300, 7923TA, 7923OR, 796600, 7966TA, 768400, 882900, 885700;
UPC: 733538715701, 733538768493, 733538792306, 733538792313, 733538796694,
733538882991, 733538885794



Sold from 1999 through March 2010

Affected buggies have pins with yellow plastic knobs on the back of the buggy. The yellow knob pin can become loose and allow the handle to separate from the buggy.

Buggies with handles attached with a bolt and screw are NOT affected.

Please inspect the buggy. If the buggy has a pin with a yellow plastic knob,

Immediately stop using the buggy and contact Step2 for a repair kit.

Call Step2 toll free at **866-860-1887**

Between 8:00 a.m. and 7:00 p.m. EST Monday through Friday or visit www.step2.com to receive a free repair kit.